VINAYAKA ENTERPRISES

Borewell Drilling Contractors

BOREWELL COMPLETION REPORT

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

Mobile : +91 9342202932 / 9343202932

No. : 770

Date : _____

1. Customer's Name and Address with Telephone No. : AEE BBMP Byatarayanapura Sub Division

2. Well Location : Vinayakanagara 1st Main 2nd Cross

3. Total Well Depth / Drilled in Ft. : 1253 feet.

4. Casing Erected in Ft. : 178 feet.

5. Water Struck at the Depth of : —

6. Total Yield (Measuring method "V" Norch : 2 inch / Inches on "V" Norch)

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear Clear

8. At the Depth of : 1100 feet.

9. Recommended to use Jet Pump / Air Compressor / Submersible /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

Scanned by CamScanner

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

Mobile : +91 9342202932 / 9343202932

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

No. : 769

Date : _____

1. Customer's Name and Address with Telephone No. : AEE BBMP. Byatarayanapura Sub division.
2. Well Location : Dharmaraya 5th Main Manj
3. Total Well Depth / Drilled in Ft. : 1273 feet.
4. Casing Erected in Ft. : 197 feet.
5. Water Struck at the Depth of :
6. Total Yield (Measuring method "V" Norch : 2 ಇಂಚು / Inches on "V" Norch)
7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear Clear.
8. At the Depth of : 1190 feet.
9. Recommended to use Jet Pump / Air Compressor / Submersible ✓ /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

Scanned by CamScanner

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

BOREWELL COMPLETION REPORT

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

Mobile : +91 9342202932 / 9343202932

No. : 768

Date : _____

1. Customer's Name and Address with Telephone No. : AEE BBMP Byatarayanapura Sub division

2. Well Location : Bagalur Enclave Yashwanthapura

3. Total Well Depth / Drilled in Ft. : 1126 feet.

4. Casing Erected in Ft. : 178 feet.

5. Water Struck at the Depth of :

6. Total Yield (Measuring method "V" Norch : 2 inch / Inches on "V" Norch)

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear Clear

8. At the Depth of : 1078 feet.

9. Recommended to use Jet Pump / Air Compressor / Submersible /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

Scanned by CamScanner

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

BOREWELL COMPLETION REPORT

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

Mobile : +91 9342202932 / 9343202932

No. : 767

Date : _____

1. Customer's Name and Address with Telephone No. : AEE BBMP Byatarayanapura Sub Div

2. Well Location : Ashwathnagar Layout SCV Apartment

3. Total Well Depth / Drilled in Ft. : 1200 feet.

4. Casing Erected in Ft. : 158 feet.

5. Water Struck at the Depth of :

6. Total Yield (Measuring method "V" Norch : 2 inch / Inches on "V" Norch)

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear Clay.

8. At the Depth of : 1109 feet

9. Recommended to use Jet Pump / Air Compressor / Submersible /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

Scanned by CamScanner

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

Mobile : +91 9342202932 / 9343202932

No. : 766

Date : _____

1. Customer's Name and Address with Telephone No. : AEE BBMP Byadarayanapura Sub Divn

2. Well Location : Agrahara Layout Main Road

3. Total Well Depth / Drilled in Ft. : 1188 feet.

4. Casing Erected in Ft. : 177 feet.

5. Water Struck at the Depth of : -

6. Total Yield (Measuring method "V" Norch : 2 inch / Inches on "V" Norch)

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear Clear

8. At the Depth of : 1020 feet

9. Recommended to use Jet Pump / Air Compressor / Submersible /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

Scanned by CamScanner

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

BOREWELL COMPLETION REPORT

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

Mobile : +91 9342202932 / 9343202932

No. : 765

Date : _____

1. Customer's Name and Address with Telephone No. : AEE BBMP Bhatarayanapura Sub division

2. Well Location : Aghrahara Layout & Municipal 3rd Cross Road.

3. Total Well Depth / Drilled in Ft. : 1178 feet

4. Casing Erected in Ft. : ~~1178 feet~~ 178 feet

5. Water Struck at the Depth of : ~~178 feet~~

6. Total Yield (Measuring method "V" Norch : 2 Inch / Inches on "V" Norch)

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear Clay.

8. At the Depth of : 1020 feet.

9. Recommended to use Jet Pump / Air Compressor / Submersible /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

~~Manager~~ / Proprietor

Scanned by CamScanner

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

Mobile : +91 9342202932 / 9343202932

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

No. : 764

Date : _____

1. Customer's Name and Address with Telephone No. : AEE Byrareddy Annapurna BBMP. Sub Divn

2. Well Location : Krishnarajapura Main Road Location

3. Total Well Depth / Drilled in Ft. : 1165 feet.

4. Casing Erected in Ft. : 197 feet.

5. Water Struck at the Depth of :

6. Total Yield (Measuring method "V" Norch : 2 inches / Inches on "V" Norch)

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear Clear.

8. At the Depth of : 1030 feet

9. Recommended to use Jet Pump / Air Compressor / Submersible /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

Scanned by CamScanner

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

Mobile : +91 9342202932 / 9343202932

BOREWELL COMPLETION REPORT

No. : 763

Date : _____

1. Customer's Name and Address with Telephone No. : AEE BBMP Byadarayanapura Sub Divn

2. Well Location : Agrahara Layout 6th main

3. Total Well Depth / Drilled in Ft. : 11" Cmt. 12 11 feet.

4. Casing Erected in Ft. : 197 feet.

5. Water Struck at the Depth of : -

6. Total Yield (Measuring method "V" Norch : 2 inch / Inches on "V" Norch)

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear Clear

8. At the Depth of : 1130 feet

9. Recommended to use Jet Pump / Air Compressor / Submersible /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report. I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

Scanned by CamScanner

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

Mobile : +91 9342202932 / 9343202932

No. : 762

Date : _____

1. Customer's Name and Address with Telephone No. : AEE BBMP Byatarayanapura Sub Divn

2. Well Location : Balaji layout Kogilu.

3. Total Well Depth / Drilled in Ft. : 1272 feet.

4. Casing Erected in Ft. : 217 feet.

5. Water Struck at the Depth of : —

6. Total Yield (Measuring method "V" Norch : 2 inch / Inches on "V" Norch)

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear clear

8. At the Depth of : 1130 feet

9. Recommended to use Jet Pump / Air Compressor / Submersible /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

Scanned by CamScanner

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 5600094

Mobile : +91 9845202952 / 9845202952

No : 761

Date : _____

1. Customer's Name and Address with Telephone No. : AEE BBMP Byatarayanapura Sub Division

2. Well Location : Prakruthi Layout 6th Cross

3. Total Well Depth / Drilled in Ft. : 200 Feets

4. Casing Erected in Ft. : 140 Feets 137 Feets

5. Water Struck at the Depth of : 137 Feets

6. Total Yield (Measuring method "V" Notch : Direct / Inches on "V" Notch)

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear Clear

8. At the Depth of : 1025 Feets

9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good satisfied / Partly agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report. I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For Vinayaka ENTERPRISES

Party's Signature

Manager / Proprietor

Scanned by CamScanner

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

Mobile : +91 9342202932 / 9343202932

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

No. : 760

Date : _____

1. Customer's Name and Address with Telephone No. : AEE BBMP Byatarayanapura Subdivision

2. Well Location : Prabhavathi Badavane near Overtank.

3. Total Well Depth / Drilled in Ft. : 1220 feet

4. Casing Erected in Ft. : 197 feet.

5. Water Struck at the Depth of : _____

6. Total Yield (Measuring method "V" Norch : 2½ inch / Inches on "V" Norch)

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear Clear

8. At the Depth of : 1170 feet.

9. Recommended to use Jet Pump / Air Compressor / Submersible /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

~~Manager~~ / Proprietor

Scanned by CamScanner

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

BOREWELL COMPLETION REPORT

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

Mobile : +91 9342202932 / 9343202932

No. : 758

Date : _____

1. Customer's Name and Address with Telephone No. : AEE BBMP Byatarayanapura.
2. Well Location : Pragathi Layout Main Road 8th Cross.
3. Total Well Depth / Drilled in Ft. : 1178 feet.
4. Casing Erected in Ft. : 217 feet.
5. Water Struck at the Depth of :
6. Total Yield (Measuring method "V" Norch : 2½" open / Inches on "V" Norch)
7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear Clear
8. At the Depth of : 1135 feet.
9. Recommended to use Jet Pump / Air Compressor / Submersible /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

Scanned by CamScanner

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

Mobile : +91 9342202932 / 9343202932

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

No. : 759

Date : _____

1. Customer's Name and Address with Telephone No. : AEE BBMP Byatarayanapura Subdivision

2. Well Location : Krishnarajapura 2nd Ward

3. Total Well Depth / Drilled in Ft. : 1260 Feet.

4. Casing Erected in Ft. : 177 Feet.

5. Water Struck at the Depth of :

6. Total Yield (Measuring method "V" Norch : 2 inch / Inches on "V" Norch)

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear Clear

8. At the Depth of : 1140 feet

9. Recommended to use Jet Pump / Air Compressor / Submersible /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

Scanned by CamScanner

No. 9, Bhadrappa Layout, [illegible]

Date : _____

No. : 757

1. Customer's Name and Address : AEE BBMP
Byatarayanapura Subdiv

with Telephone No.

2. Well Location : Srirampura Kalyana Mantapa

3. Total Well Depth / Drilled in Ft. : 1200 feet

4. Casing Erected in Ft. : 236 feet

5. Water Struck at the Depth of :

6. Total Yield (Measuring method "V" Norch : 2 inch / Inches on "V" Norch)

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear clear

8. At the Depth of : 1110 feet

9. Recommended to use Jet Pump / Air Compressor / Submersible /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

~~Manager~~ / Proprietor

Scanned by CamScanner